

<b>Title:</b>	DS-76xxNI-E1(#2)P v3.0.7 build 20150303 Release Notes	<b>Version:</b>	1.0	<b>Date:</b>	
<b>Product:</b>	3535 Series NVR (DS-7604NI-E1/4P and DS-7608NI-E2/8P)				
<b>Action Required:</b>	None, Information Only				

### 3535 Series NVR Firmware Information:

Firmware Version: v3.0.7, build 150203, Encode Version: v5.0, build 140819

### 3535 Series NVR Model:

DS-7604NI-E1/4P and DS-7608NI-E2/8P

### Compatible IP Camera Information:

IP Camera Model	IP Camera Firmware
Raptor DS-2CD2xxx Series	V5.2.0_140721
Raptor DS-2CD4xxx Series	V5.2.0_140721
DS-2CD63xx Series	V5.0.9_140612
DS-2CD64xx Series	V5.2.0_140721
DS-2CD7xx/72xx/8xx/82xx Series	V5.2.0_140721
DS-2CD2942F-I(S)	V5.2.1_141120

### 3535 Series NVR v3.0.7 Firmware Updates:

1. Fully compatible with DS-2CD2942F-I(S) new fisheye camera.
2. Ports 65xxx for virtual host are modifiable. Image if we have two NVRs for one location, only one virtual host will work if these ports are not modifiable.
3. In Camera Setup -> Image for settings like WDR, Backlight Compensation, and Video Adjustment Mirror can use the words On and Off instead of Enable and Close.
4. Adds Enable Virtual Host setting in network settings on NVR GUI.
5. Fixes the buffer overflow issue.
6. Live view 2x2 is using sub-stream.