

Product Name	Affected Vuls	Affected Versions	Upgrade to the latest Firmware Version to fix it
DS-K1T804AXX	CVE-2023-28809 & CVE-2023-28810	Versions below V1.4.0_build221212 (including V1.4.0_build221212)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T804A/V1.4.0_build230403">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T804A/V1.4.0_build230403</a>
DS-K1T341AXX		Versions below V3.2.30_build221223 (including V3.2.30_build221223)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T341A/DS-K341A%20-%20Baseline%20Mask%20Detection/V3.2.30_build230330">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T341A/DS-K341A%20-%20Baseline%20Mask%20Detection/V3.2.30_build230330</a>
DS-K1T671XXX		Versions below V3.2.30_build221223 (including V3.2.30_build221223)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T671/V3.2.30_build230330">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T671/V3.2.30_build230330</a>
DS-K1T343XXX		Versions below V3.14.0_build230117 (including V3.14.0_build230117)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T343/V3.14.0_build230331">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T343/V3.14.0_build230331</a>
DS-K1T341C		Versions below V3.3.8_build230112 (including V3.3.8_build230112)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T341C/V3.3.8_build230330">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T341C/V3.3.8_build230330</a>
DS-K1T320XXX		Versions below V3.5.0_build220706 (including V3.5.0_build220706)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T320/V3.5.1_build230531">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/06%20%20Access%20Control/00%20%20Product%20Firmware/Terminal/DS-K1T320/V3.5.1_build230531</a>

Product Name	Affected Vuls	Affected Versions	Upgrade to the latest Firmware Version to fix it
DS-KH6320-LE/TE(B) Series DS-KH6350 Series	CVE-2023-28810	Versions below V2.2.8_build230219 (including V2.2.8_build230219)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH6320-LE1%28B%29%20KH6350%20KH6360%20-%28TE1%29/V2.2.20_230601">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH6320-LE1%28B%29%20KH6350%20KH6360%20-%28TE1%29/V2.2.20_230601</a>
DS-KH8350 Series DS-KH6320-TE Series DS-KH8520 Series		Versions below V2.2.8_build230219 (including V2.2.8_build230219)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH6320-%28W%29TE1%20KH8350%20KH8520-%28TE1%29/V2.2.20%20Build230601%20Protocol%202.0">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH6320-%28W%29TE1%20KH8350%20KH8520-%28TE1%29/V2.2.20%20Build230601%20Protocol%202.0</a>
DS-KH9310-WTE1(B) DS-KH9510-WTE1(B)		Versions below V2.1.76_build230204 (including V2.1.76_build230204)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH9310%28B%29%20KH9510%28B%29/V2.1.80_build230320">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH9310%28B%29%20KH9510%28B%29/V2.1.80_build230320</a>
DS-KH8301 Series DS-KH8300 Series DS-KH6310 Series DS-KH6210 Series		Versions below V1.5.1_build191024 (including V1.5.1_build191024)	<a href="https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH8301%20KH8300%20KH6310%20KH6210%20EOL/V1.5.1%20Build%20230626">https://www.hikvisioneurope.com/eu/portal/?dir=portal/Technical%20Materials/07%20%20Video%20Intercom/00%20%20Product%20Firmware/02%20Indoor%20Station%20%28KH%29/KH8301%20KH8300%20KH6310%20KH6210%20EOL/V1.5.1%20Build%20230626</a>