

# G3 Network PTZ Dome Camera Firmware

## Version: V5.5.26 Release Note

(2020-12-09)

### 1. Firmware Version Information

#### 1.1 Firmware Basic Information

PTZ:

IPD\_G3\_EN\_XXX\_5.5.26\_200713.zip

#### 1.2 1.2 Support model

Only support released model.

### 2. Related Resource Versions

#### 2.1 Built-in Resource Versions

- (1) SDK version: HCNetsDKV6.1.4.40\_build20200428\_Win32\_ZH.zip
- (2) Play lib (PlayCtrl.dll): V7.3.8.42
- (3) iVMS 4200 client: V3.3.2.2
- (4) Plugin:
  - STD: V4.0.1.0 build 200629
  - NEU: V4.0.1.1 build 200629

#### 2.2 Protocol Versions

- (1) Onvif version: 18.12
- (2) ISAPI version: 2.4
- (3) ISUP version: V2.0, V4.0, ISUPV5.0

- (4) CGI: V2.0
- (5) Hik-Connect version: V1.7

## 2.3 Third-party Platform Software Versions

- (1) Milestone software version (Milestone Enterprise 8.1a(2016 R2 10.2a)), Milestone driver version (Device Pack 9.6)
- (2) Milestone software version (Milestone Corporate 2018 R2), Milestone driver version (Device Pack 10.2)
- (3) Exacqvision software (v19.03.6.152839)
- (4) Avigilon Control Center v6.14.4.6

## 3. Version Main Updates

### 3.1 New Features

- **New models are released.**

**New release DE3A model:**

**DS-2DE3A400BW-DE(F1)(O-STD)(S5)**

**DS-2DE3A400BW-DE/W(F1)(O-STD)(S5)**

**Compared with 5.5.23:**

1. **Support Patrol function (Speed 1-40, Time 120s-3600s, 120s by default)**
2. **Delete menu and Preset 95;**
3. **Brightness limit: Indoor 50, other scene 100.**

### 3.2 Improved Features

None

### 3.3 Leftover Issues

None

## Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

### **Remarks:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)