

Thermal Network Bullet Camera & Turret Camera

Version: V5.5.22 build 210123

Release Notes

(2021-01-23)

Index

1. General Information	3
2. New Features	3
2.1 Fixed Malfunctioning of Brightness Sudden Change Suppression	3
2.2 Fixed Inaccurate Temperature Detection	3
3. Supported Product List.....	3

1. General Information

Firmware Version	V5.5.22 build 210123
SDK Version	V6.1.5.35 build20200908
Play Lib	V7.3.9.41 Win32_Base_Build20200716
iVMS-4200	V3.2.2.103 build20200903
Web Component/ Plugin Version	V4.0.1 build 200908/3.0.7.35

2. New Features

2.1 Fixed Malfunctioning of Brightness Sudden Change Suppression

Brightness Sudden Change Suppression would be refreshed when a user changes image settings. The refreshed status is OFF, while the user interface presents ON.

2.2 Fixed Inaccurate Temperature Detection

Detected temperature value was obviously lower than real temperature. The bug has been fixed.

3. Supported Product List

DS-2TD1217-2/V1	DS-2TD1217-3/V1	DS-2TD1217-6/V1	
DS-2TD2617-3/V1	DS-2TD2617-6/V1		
DS-2TD2836-25/V1	DS-2TD2836-50/V1		
DS-2TD2866-25/V1	DS-2TD2866-50/V1		
DS-2TD2117-3/V1	DS-2TD2117-6/V1		
DS-2TD2136-7/V1	DS-2TD2136-10/V1	DS-2TD2136-15/V1	DS-2TD2136-25/V1
DS-2TD2136-35/V1			
DS-2TD2166-7/V1	DS-2TD2166-15/V1	DS-2TD2166-25/V1	DS-2TD2166-35/V1
DS-2TD2137-4/V1	DS-2TD2137-7/V1	DS-2TD2137-10/V1	DS-2TD2137-15/V1
DS-2TD2137-25/V1	DS-2TD2137-35/V1		
DS-2TD2836-25	DS-2TD2836-50	DS-2TD2866-25	DS-2TD2866-50
DS-2TD2615-7	DS-2TD2615-10		
DS-2TD2636-10	DS-2TD2636-15		
DS-2TD2636T-10	DS-2TD2636T-15		
DS-2TD2137-7/VP	DS-2TD2137-10/VP	DS-2TD2137-15/VP	DS-2TD2137-25/VP
DS-2TD2137-35/VP			