

HIKVISION



Hybrid SAN 236-2 Release Note Document

Release Note

COPYRIGHT ©2017 Hangzhou Hikvision Digital Technology Co., Ltd.

ALL RIGHTS RESERVED.

Any and all information, including, among others, wordings, pictures, graphs are the properties of Hangzhou Hikvision Digital Technology Co., Ltd. or its subsidiaries (hereinafter referred to be “Hikvision”). This release note (hereinafter referred to be “the Manual”) cannot be reproduced, changed, translated, or distributed, partially or wholly, by any means, without the prior written permission of Hikvision. Unless otherwise stipulated, Hikvision does not make any warranties, guarantees or representations, express or implied, regarding to the Manual.

About this Manual

This Manual is applicable to Hybrid SAN 236-2.

The Manual includes instructions for using and managing the product. Pictures, charts, images and all other information hereinafter are for description and explanation only. The information contained in the Manual is subject to change, without notice, due to firmware updates or other reasons. Please find the latest version in the company website (<http://overseas.hikvision.com/en/>).

Please use this user manual under the guidance of professionals.

Trademarks Acknowledgement

HIKVISION and other Hikvision’s trademarks and logos are the properties of Hikvision in various jurisdictions. Other trademarks and logos mentioned below are the properties of their respective owners.

Legal Disclaimer

TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, THE PRODUCT DESCRIBED, WITH ITS HARDWARE, SOFTWARE AND FIRMWARE, IS PROVIDED “AS IS”, WITH ALL FAULTS AND ERRORS, AND HIKVISION MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY, SATISFACTORY QUALITY, FITNESS FOR A PARTICULAR PURPOSE, AND NON-INFRINGEMENT OF THIRD PARTY. IN NO EVENT WILL HIKVISION, ITS

DIRECTORS, OFFICERS, EMPLOYEES, OR AGENTS BE LIABLE TO YOU FOR ANY SPECIAL, CONSEQUENTIAL, INCIDENTAL, OR INDIRECT DAMAGES, INCLUDING, AMONG OTHERS, DAMAGES FOR LOSS OF BUSINESS PROFITS, BUSINESS INTERRUPTION, OR LOSS OF DATA OR DOCUMENTATION, IN CONNECTION WITH THE USE OF THIS PRODUCT, EVEN IF HIKVISION HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

REGARDING TO THE PRODUCT WITH INTERNET ACCESS, THE USE OF PRODUCT SHALL BE WHOLLY AT YOUR OWN RISKS. HIKVISION SHALL NOT TAKE ANY RESPONSIBILITIES FOR ABNORMAL OPERATION, PRIVACY LEAKAGE OR OTHER DAMAGES RESULTING FROM CYBER ATTACK, HACKER ATTACK, VIRUS INSPECTION, OR OTHER INTERNET SECURITY RISKS; HOWEVER, HIKVISION WILL PROVIDE TIMELY TECHNICAL SUPPORT IF REQUIRED.

SURVEILLANCE LAWS VARY BY JURISDICTION. PLEASE CHECK ALL RELEVANT LAWS IN YOUR JURISDICTION BEFORE USING THIS PRODUCT IN ORDER TO ENSURE THAT YOUR USE CONFORMS THE APPLICABLE LAW. HIKVISION SHALL NOT BE LIABLE IN THE EVENT THAT THIS PRODUCT IS USED WITH ILLEGITIMATE PURPOSES.

Catalog

1	Upgrade scope	5
●	Version information.....	5
●	Hybrid SAN Models	5
2	Upgrade content	5

1 Upgrade scope

- Version information

Hybrid SAN 236-2

- Hybrid SAN Models

DS-A80624S DS-A81016S

DS-A82024D

DS-A72024R DS-A72072R

2 Upgrade content

【Hybrid SAN】 Fix VMS shows hybrid san offline issue.

【Hybrid SAN】 Fix the defect that the N+1 configuration cannot synchronize the encoder to the standby.

【Hybrid SAN】 ONVIF type encoder supports H265 video format.

【Hybrid SAN】 Support filtering recording strategy on Hybrid san system.

【Hybrid SAN】 Optimize the video timing back transmission function, add frame analysis, and solve the problem that the video packaging time is inconsistent with the video playback time.

【Hybrid SAN】 Users can set the recording time to query the total duration, for example, set for 30 days, that is, only 30 days of recording can be found in the Hybrid san storage.

【Hybrid SAN】 Optimize dual control takeover time within 1 minute.

【Hybrid SAN】 The upgrade package is released to be compatible with the above version 234-3 (included).

【OS】 Solve page download log timeout issue.

【OS】 Repair product environment control table abnormal issue.

【OS】 Optimize SADP discovery storage device logic, Avoid Hybrid san can't be found in SADP

【OS】 The dual-control Hybrid san turns off the disk hibernation function and shields the disk hibernation configuration page.

【OS】 Hybrid san disables disk hibernation by default

【OS】 Solve the problem that when mdvr upload the video, restart mdvr or the network interrupt does not continue to upload.

【Firmware】 Even if the device is upgraded with incompatible firmware, the device can be booted normally.

【Firmware】 Update the latest disk compatibility list to support up to 12TB