

DS-KB8112-IM V1.4.5 build190219

Release Note

Reason of Upgrade

Added or modified functions, enhance products quality and meet customers' requirements.

Modified Features

1. Improved day-night mode switching speed;
2. If device change day-night status more than 5 times in 10 minutes, the day-night status will be freezed, device will not change status anymore until 1 hour later.

Fixed Bugs

1. Fix a bug that when device is monitoring by NVR or iVMS or indoor station, the day-night mode can not be changed.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com